


## Notice regarding Asbestos in TOWA Equipment


An internal audit has found that products containing asbestos were used in the manufacture of the TOWA systems shown in the table below.

1. Systems that were built with products containing asbestos

- (1) Mold dies, frame loaders, and other molding systems manufactured through 1989 used thermal insulation plates that contained asbestos.
- (2) Y-Series systems manufactured through 1998 used heater lead wires that contained asbestos.



**Method of identifying heater lead wire that contains asbestos**



If you are currently using a molding system that may contain asbestos based on the information described above, please contact your local TOWA Service Department for information regarding how to safely perform maintenance or removal of the parts containing asbestos.

2. All current TOWA products are completely free of asbestos.